

Service Information



Special Tools & Equipment

Number: ATE-20-15


Subject: T40093/5 RECALL – Inspection Needed

Date: August 7, 2020

This communication is intended for Dealers that have not completed the inspection of T40093/5 that was previously communicated via email to Service Managers, Shop Foremen, and Parts Managers. Only one response per Dealer is required.

Service Tools & Equipment is in need of your assistance in locating and inspecting tool T40093/5 for a third weld. **NOTE:** you may have more than one T40093/5. Inspection of ALL T40093/5 is needed.

In the event of a complete malfunction of the T40093/5, the engine supported with T40093/5 will fall. Consequently, service personnel may sustain injuries and damage to the vehicle may occur. If the T40093/5 has the **third weld**, Please **DISCONTINUE USE IMMEDIATELY!** Set aside the effected T40093/5 for return and replacement.



The presence of a third weld indicates replacement is needed.

Please EMAIL the requested information below to ST&E promptly at -

VWGoAWorkshopEquipment@vw.com

Please provide the requested information below and attach photos of YOUR T40093/5 whether or not it needs to be replaced.

1. Dealer Code
2. Manager/Foreman Name & DIRECT contact phone number
3. Manufacture Code
4. Number of T40093/5 that NEED REPLACED
5. Two photos of EACH T40093/5 - One Showing the **3rd WELD/Lack of 3rd weld**, and One of the **manufacture** code.



T40093/5 is a component unit for the sets T40093, T40093A and T40093B, as well as individually as a replacement part. T40093/5 has been superseded by the new development T40093/5A.

Note: T40093C includes the updated T40093/5A and is NOT part of this action.

Service Information



Please identify if your T40093/5 has the **third weld** as shown below, and identify as one of the following **manufactures**.



WEMA / MA



CI / MA



CE / MA



SPX / MA



Beissbarth-C49 / MA